HOT SHEET 3-WHEEL ELECTRIC





8FBE15-20U

KEY TOYOTA POINTS:

- **Proven Performance** Comprehensive cycle testing shows that Toyota's 8FBE20U model moves 9.89% more pallets than the Hyster J40XNT, effectively increasing your productivity.*
- **Welcome Aboard:** Low step heights, ample step and floor surfaces, and large dual operator assist grips improve entry and exit and reduce fatigue.
- **Comfortably in Control:** Thoughtfully designed, cowl-mounted hydraulic controls with auto-fork levelling reduces operator fatigue and improves productivity.
- **Get Your Motor Running:** Toyota designed and built AC drive and pump motors provide superior durability, reliability, and performance.
- **A Visible Difference:** Toyota offers superior visibility in all directions thanks to a wider mast window, rollformed overhead guard pillars, and clear sightlines to elevated loads.

*Testing based on both loaded and unloaded travel with both forklifts in "Performance" mode and similar forklift configurations.

CLASS

TOYOTA COMPETITIVE ANALYSIS

TOYOTA 8FBE20U

► **HYSTER** J40XNT





Active Mast Control monitors lift height and load weight, automatically reacting to limit or prevent tilt and reduce the likelihood of a tip over.



I.

No Active Mast Control or automatic fork leveling.



Hood-mounted controls are large, clunky, and require more effort to operate.

Main controller is designed and manufactured by Toyota and protected behind the battery compartment from moisture and debris.

Hydraulic controls are cowl-mounted, do not impede entry/exit,

and require little effort for operation.

Standard 4-way adjustable vinyl full-suspension seat with side bolsters improves overall operator comfort.

Two-piece, no-tools-required floorboard and easy access components reduce service time.

Multi-function display mounted conveniently on the dash for ease of access.



. . .

Main controller is mounted under the floor board, which is harder to access and susceptible to dust/debris.

Standard non-suspension seat with hip restraints reduces operator comfort and impedes entry/exit.

Four-piece floorboard and difficult access to dip sticks make service more time consuming.

Overhead guard mounted multi-function display is hard to reach and houses the ignition.

